

SEWING MACHINE TABLE
COMFORT NEXT
СТОЛ ДЛЯ ШВЕЙНОЙ МАШИНЫ



SYMBOLS



ATTENTION

ВНИМАНИЕ




ASSEMBLY & ADJUSTMENT

СБОРКА РЕГУЛИРОВКА




OPERATION

ЭКСПЛУАТАЦИЯ



INDICATING MARK















ОБОЗНАЧЕНИЕ








EVEN SURFACE


РОВНАЯ ПОВЕРХНОСТЬ


010001	1 X	010003	1 X	010004	1 X
010006	1 X	010007	1 X	010013	1 X
010015	1 X	010023	1 X	010024	1 X
010025	1 X	010026	1 X	010027	1 X
010032	1 X	010038	1 X	010039	1 X
010040	1 X	010043	1 X		

 020001 2x		 020002 2x							
2x  020004	2x  020005	2x  020006	1x  020011	1x  020012	4x 020018 				
2x 020013 CR 		2x 020013 CL 		2x 020016 		020021  4x			
2x 020015 DL 		2x 020015 DR 							

030001 10x  3 * 16	030002 40x  3,5 * 16	030003 18x  6,2 * 50	030005 2x  4,2 * 16	030006 6x  2,9 * 13	030008 4x  φ 4	030004 4x  φ 5 * 30	
030009 4x  M4 * 20	030011 18x  φ 15	030012 12x  φ 18	12x 030013  L 35	030014 12x  φ 15 h 12			
2x 030015  φ 8 * 30	2x 030016  φ 8 * 30	030017 2x  φ 15 h 12	030022 4x  M 10	030023 4x  φ 10	4x 		

<p>1x 050002</p> 	<p>1x 050004</p> 	<p>1x 050005</p> 
<p>1x 050003</p> 		
<p>S4 1x</p> 		








14 4x 030011
4x 030003

17
6x 030013

13
030002 4x
2x 020013 CR

18
6x 030014
6x 030012



13
020013 CL 2x
030002 4x

16 6x 030011
6x 030003

15
4x 030022
4x
4x 030023
4x 020021

